



Case History QA/QC Inspection

**SPERLING
HANSEN
ASSOCIATES**

Hartland Landfill QA/QC Inspection

- *Over 8 ha of 40 mil PVC membrane was installed in 1996.*
- *SHA personnel provided continuous QA/QC inspection.*
- *Services were critical to ensure integrity of cover system.*
- *Testing included seam strength and seam quality following ASTM protocols and SHA's comprehensive QA/QC manual.*
- *Design developed and proven with test pads.*

CRD Contact: Chris Riddell (250) 727-3331



SPERLING HANSEN ASSOCIATES
#8-1225 East Keith Road, North Vancouver, B.C.
Phone (604) 986-7723 Fax (604) 986-7734
E-Mail: sperling@sperlinghansen.com

- **Landfill Siting**
- **Landfill Closure**
- **Hydrogeological Investigations**
- **Environmental Monitoring**
- **Design and Operations Plans**