



Case History STABILITY ASSESSMENT

**SPERLING
HANSEN
ASSOCIATES**

Slope Stability Assessment for Port Mann Landfill

A slump occurred along north face of landfill.

- *SHA investigated the site to determine the probable cause of failure.*
- *SHA provided recommendations to improve slope design and minimize the risk of future failures.*

City of Surrey Contact: **Mr. Robert Castanza (604)-590-7287**
Project Budget: **\$2 000**



SPERLING HANSEN ASSOCIATES

#8-1225 East Keith Road, North Vancouver, B.C.
Phone (604) 986-7723 Fax (604) 986-7734
E-Mail: sperling@sperlinghansen.com

- **Landfill Siting**
- **Landfill Closure**
- **Hydrogeological Investigation**
- **Environmental Monitoring**
- **Design and Operations Plans**